# Designer Square Suction for Self-Contained Spas INSTALLATION INSTRUCTIONS

For Model Number: BU64012XX-VP



### WARNING:

IMPORTANT SAFETY INSTRUCTIONS. READ, UNDERSTAND, AND FOLLOW ALL WARNINGS AND INSTRUCTIONS. SAVE THESE INSTRUCTIONS.

Read and follow all instructions in this owner's manual and on the equipment. Failure to follow instructions can cause severe injury and/or death.

# **SOFA INSTRUCTIONS**

When installing and using this equipment, basic safety precautions shall always be followed, including the following: IMPORTANT SAFETY INSTRUCTIONS. READ, FOLLOW, AND UNDERSTAND ALL INSTRUCTIONS AND WARNINGS.

Any modification that increases the flow rate of the circulation system shall require re-evaluation of the cover/grate and sump to ensure that the flow rating of the Suction Outlet Fitting Assembly (SOFA) is not exceeded.

Missing, broken, or cracked cover/grates, sumps, mud-frames, or any other SOFA component shall be replaced before bathers are allowed to use the pool.

Loose cover/grates shall be reattached before bathers are allowed to use the pool. SAVE THESE INSTRUCTIONS.

# **IMPORTANT SAFETY INSTRUCTIONS:**



**WARNING - SUCTION ENTRAPMENT HAZARD** Suction in suction outlets and/or suction outlet covers which are damaged, broken, cracked, missing, or unsecured can cause severe injury and/ or death due to the following entrapment hazards:

Hair Entrapment: Hair can become entangled in suction outlet cover.

**Limb Entrapment:** A limb inserted into an opening of a suction outlet sump or suction outlet cover that is damaged, broken, cracked, missing, or not securely attached can result in a mechanical bind or swelling of the limb.

**Body Suction Entrapment:** A negative pressure applied to a large portion of the body or limbs can result in an entrapment.

**Evisceration / Disembowelment Entrapment:** A negative pressure applied directly to the intestines through an unprotected suction outlet sump or suction outlet cover which is damaged, broken, cracked, missing, or unsecured can result in evisceration / disembowelment entrapment.

**Mechanical Entrapment:** There is potential for jewelry, swimsuit, hair decorations, finger, toe, or knuckle to be caught in an opening of a suction outlet cover resulting in mechanical entrapment.

## **USE ONLY GENUINE WATERWAY REPLACEMENT PARTS.**




©2025 Waterway Plastics



2200 East Sturgis Road, Oxnard CA 93030 • Phone 805.981.0262 • Fax 805.981.9403 www.waterwayplastics.com • waterway@waterwayplastics.com

# TO REDUCE THE RISK OF ENTRAPMENT HAZARDS:



• A minimum of two functioning suction outlets per pump must be installed. Suction outlets in the same plane (i.e. floor or wall) must be installed a minimum of three feet (3') / 1 meter apart, as measured from

suction pipe center to suction pipe center.

- Dual suction fittings shall be placed in such locations and distances to avoid "dual blockage" by a user.
- Dual suction fittings shall not be located on seating areas or on the backrest for such seating areas.
- The maximum system flow rate shall not exceed the flow rating of any listed (per ASME A112.19.8-2007, APSP-16) suction outlet cover installed. In the event of one suction outlet being completely

blocked, the remaining suction outlets serving the system shall have a flow rating capable of the full flow of the pump(s).

- Never use a pool or spa if any suction outlet component is damaged, broken, cracked, missing, or not securely attached.
- Replace damaged, broken, cracked, missing, or not securely attached suction outlet components immediately.
- Two or more suction outlets per pump should be installed in accordance with latest APSP Standards and CPSC guidelines, and follow all National, State, and Local codes applicable.
- Replace the suction within 7 years from the installation date.
- Installation of a vacuum release system, which relieves entrapping suction, is recommended.

# WARNING



Failure to remove pressure test plugs and/or plugs used in winterization of the pool/spa from the suction outlets can result in an increased potential for suction entrapment as described on the previous page.



Failure to keep suction outlet components clear of debris, such as leaves, dirt, hair, paper and other material, can result in an increased potential for suction entrapment as described on the previous page.



Suction outlet components have a finite life. The cover/grate should be inspected frequently and replaced at least every seven years, or if found to be damaged, broken, cracked, missing, or not securely attached.



The BU64012XX-VP fitting is rated at 225 GPM. If the fitting is missing or broken, replace with a fitting of equivalent rating or higher. Use of a lower rated suction fitting could result in entrapment of the body which could result in serious injury including drowning.



Do not use or operate spa/hot tub if this suction fitting is missing, broken or not secured per instructions. The suction fitting is intended to prevent entrapment of the body. Use of the spa hot tub with a missing, broken or improperly secured suction grate may result in serious personal injury including drowning.



When the spa or hot tub is in operation, suction is created at this fitting. Users of the spa or hot tub must be instructed not to come in contact with this fitting in such a way as to block its orifice. If a user of the spa or hot tub blocks this fitting with his/her body, serious personal injury or drowning may occur.



Self-contained spa fittings should be used in Self-Contained Factory Manufactured Spas only and at least two suction fittings should be used for each pump.

# **INSTALLATION INSTRUCTIONS**


1. Locate and cut a 3 <sup>1</sup>/<sub>4</sub>" hole in a vertical wall of the spa. Be sure the area located is flat and spa laminate thickness is uniform.


- 2. Insert wallfitting with gasket through hole.
- 3. Apply a bead of silicon against the back wall of the spa and around the threads of the wall fitting . Avoid getting sealant on gasket.
- 4. Install nut and tighten. Be sure wallfitting screw studs are horizontal to bottom of spa.
- 5. Glue elbow supplied with fitting into wallfitting. Be sure to orient the elbow in the required direction while gluing.



WARNING: This is a PVC to PVC connection. Improper gluing or improper cement selection can cause leaks at glued connection which can result in property damage.

NOTE: The size of the plumbing shall not be reduced for at least 16" after the point of connection to shown wallfittings.





#### WARRANTY

For product registration visit: www.waterwayplastics.com. For Warranty questions or claims please contact point of purchase.

## FLOW PATH ZONE DIMENSIONS:

This is a sumpless drain.



NOTE: Use of field fabrication sumps is not permitted



©2025 Waterway Plastics



2200 East Sturgis Road, Oxnard CA 93030 • Phone 805.981.0262 • Fax 805.981.9403 www.waterwayplastics.com • waterway@waterwayplastics.com

# Installation Information Label 5" Designer Square Suction

Cover/Grate Model#: BU64012XX-VP Life & years from the date of installation: 7 Years

Flow Ratings Wall Flow Rate: 225 GPM Installer shall fill-in the location of the installed SOFA and the cover/grate Installation before giving this information label to the pool owner. This Installation Information Label shall be permanently posted as near feasible to the pump control, and that a copy of this information be given to the pool owner, to be kept with other important pool related documents.

Location of the Installed SOFA, such that it can be successfully identified in the future:

The date the cover/grate was installed in the pool, where the month and year indicators on the label are easily activated in the field:

## 5" Designer Square Suction: BU64012XX-VP

Wall Flow Rate: 225 GPM

#### Removable Tags for Blockable Cover/Grate Packaging

"READ, FOLLOW, AND UNDERSTAND ALL INSTRUCTIONS AND WARNINGS". This VGBA Suction outlet has an installation specific flow rating and this product SHALL NOT be installed on a pumping system that is capable of exceeding this limit, which varies based on the number and location of installed suction outlets. READ and FOLLOW this section of the included installation instructions explaining how to calculate the suction system flow ratings and that of the installed pumping system.

A "WARNING! This is a BLOCKABLE VGBA Suction Outlet that must ONLY be installed in a multiple VGBA Suction Outlet System." (9.8.2.1)

This is a BLOCKABLE VGBA Suction Outlet. It must ONLY be installed in a suction system that also includes one or more of the following devices or systems designed to prevent suction entrapment, when and if the suction cover marked for single use and used as the sole source of water for a single suction outlet :

- Safety Vacuum Release System
- Suction Limiting Vent System
- Gravity Drainage System
- Automatic Pump Shut-Off System
- Drain Disablement
- Other Systems determined by Consumer Product Safety Commission to be equally effective as , or better than
  above-mentioned systems at preventing or eliminating the risk of injury or death associated with pool drainage system.

THIS TAG/LABEL IS TO BE CUT & REMOVED BY THE INSTALLER ONLY

# **GENERAL CERTIFICATE OF COMPLIANCE**

## **DESIGNER SQUARE SUCTION: BU64012XX VP**

Contents:	1	
Model Number:	BU64012XX VP Wall Only	
Description:	Designer Square Suc	tion
Wall Flow Rate:	225 GPM	<b>U</b> VGBA 2017
For Dat		the manufacture mark on product
	$\begin{array}{c} & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ \end{array}$	the manufacture mark on product
Date o	$\int_{a}^{1^2 / 3} \int_{a/2}^{1} \int_{a/2}^{15} \int_{a/2}^{1} \int_{a/2}^{15} \int_{a/2}^{1} \int_{a/2}^{1$	
Date o Name	$\int_{8}^{1^{2}/3} \int_{8}^{1} \int_{9}^{1} \int_{9}^{1} \int_{9}^{1} \int_{1}^{1} \int_{8}^{1} \int_{8}^{1} \int_{1}^{1} \int_{8}^{1} \int_{1}^{1} \int_{1}^{1$	
Date o Name Signat This product has been to Graham Baker Pool and	sted, certified and listed to the requ	·
Date o Name Signat This product has been to Graham Baker Pool and Brea, CA 92821-6729 This product is certified	$s_{2}^{1}$ $s_{2}^{1}$ $s_{3}^{1}$ $s_{4}^{1}$ $s_{5}^{1}$ $s_{5}^{1}$ $s_{2}^{1}$ $s_{2}^{1}$ $s_{2}^{1}$ $s_{2}^{1}$ $s_{4}^{1}$ $s_{4$	irements of ANSI/APSP - 16. 2017 per §1404 of the Virginia
Date o Name Signat This product has been to Graham Baker Pool and Brea, CA 92821-6729 This product is certified the test results for the a The test results support	f Installation: of Installation: of Installer: ure of Installer: ested, certified and listed to the requ Spa Safety Act. Certified by: Underw to comply with §1404 of the Virginia bove may be found at www.waterw	uirements of ANSI/APSP - 16. 2017 per §1404 of the Virginia vriters Laboratories, Inc., 2929 E. Imperial Highway, Suite 100, a Graham Baker (VGBA 2017) Pool and Spa Safety Act. A copy of vayplastics.com or go to: www.ul.com. ntained by Ray Mirzaei, 2200 Sturgis, Rd, Oxnard , CA 93030





2200 East Sturgis Road Oxnard CA 93030 • Phone 805.981.0262 • Fax 805.981.9403 waterway@waterwayplastics.com • www.waterwayplastics.com